


P35046
1/35

BSA M20 **Motorcycle** **Correction Set** for Tamiya kit



3D-Printed Parts



Special Hobby 2026

Resinové díly ohnuté popř. pokroucené vlivem teplotních změn a stárnutí materiálu, mohou být narovnány do požadovaného tvaru pomocí proudu teplé vody nebo vzduchu (fén na vlasy). Ohnuté 3D tisky narovnejte ponořením do horké vody, srovnejte je a zchladte studenou vodou. K lepení použít kyanoakrylátové lepidlo! Kontaktní plochy doporučujeme před lepením odmastit.
Různé drátky a tyčinky nejsou přiloženy.

Parts slightly distorted and bent owing to temperature changes or due to material aging can be straightened to requested shape by hot water or hot air jet (hair dryer). This process can be repeated till result is entirely satisfactory. You can also correct bent 3D printed parts: put them into hot water, straighten them and cool them in cold water. For best result use cyanoacrylate glue! Ungreasing contact areas is recommended before gluing. Wires and rods not included.

Special Hobby offer 1/35 P35040 DKW NZ 350
Correction Set for Tamiya kit 35241 as well



Other 1/35 motorcycle kit sets **in the Special Hobby range**

P35031

Zündapp KS 600 Wheels / for Tamiya kit



P35034

Zündapp KS 750 Wheels

P35035


Zündapp KS 750 MG 34 with gun mount
and magazine carrier

P35036

Zündapp KS 750 Metal Transport Boxes

P35037

Zündapp KS 750 Headlights, drawbar
and other improvements
for Academy kit



info at www.specialhobby.eu